## National Transportation Safety Board NTSB ID: DEN02LA103 Aircraft Registration Number: N551SA FACTUAL REPORT Most Critical Injury: Fatal Occurrence Date: 09/08/2002 AVIATION Occurrence Type: Accident Investigated By: NTSB Location/Time Nearest City/Place State Zip Code Local Time Time Zone 80542 0930 CO MDT Mead Distance From Landing Facility: Direction From Airport: Airport Proximity: Off Airport/Airstrip Aircraft Information Summary Aircraft Manufacturer Model/Series Type of Aircraft Adler SA-1 Gyrocraft

## Narrative

Sightseeing Flight: No

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On September 8, 2002, approximately 0930 mountain daylight time, an Adler SA-1 gyroplane, N551SA, registered to and operated by the pilot, was destroyed when it impacted terrain and burned near Mead, Colorado. The private pilot was fatally injured. Day visual meteorological conditions prevailed, and no flight plan had been filed for the personal flight being conducted under Title 14 CFR Part 91. The local flight originated approximately 0900 from the Jefferson County (Jeffco) Airport, Broomfield, Colorado.

Air Medical Transport Flight: No

Two witnesses told a sheriff's deputy that the gyroplane sounded as if it was "struggling." Two other witnesses submitted written statements. One witness said that he "could tell the aircraft was having mechanical problems." The gyroplane dropped about 1,000 feet, "lost a wing" and began to "spin and tumble out of control." Another witness said he heard the engine either "miss or stall slightly," and also saw "a rotor or a wing" come off in flight. All four witnesses saw smoke as the gyroplane impacted terrain and immediately caught fire.

According to the deputy's report, a rotor blade was found about 150 feet north of the point of impact, and other debris was strewn to the southwest. The impact site was circular in shape, approximately 5 to 6 meters (16 to 20 feet) in diameter. The accident occurred 0.25-mile south of (Weld) county road 32 and 0.25-mile west of county road 13, at a location of 40 degrees, 12'48.30" north latitude, and 104 degrees, 57'02.80" west longitude.

The co-builder of the accident gyroplane --- a physician and a close friend of the pilot --- contacted three gyroplane experts: the designer of the SA-1 Dominator and President of Rotor Flight Dynamics; a gyroplane aerodynamist; and the designer of another gyroplane. They examined the wreckage and compiled both a factual and analytical report. The following is based on the factual portion of the report.

The separated rotor blade was bowed upward and had fractured about 2 feet from the tip. The fracture was consistent with positive overload. There was orange paint and primer transfer marks on the top and upper leading edge (the tail and nose cones were painted orange). The attached rotor blade was also bent upward. The propeller blades exhibited no strike marks. The rotor head and hub bar were intact. The hub bar, normally bent 2.5 degrees upward, was found bent approximately 10 degrees upward. The roll pillow blocks bore evidence of hammering and were mushroomed. The pitch stops were similarly damaged.

The analytical portion of the report noted the necessity of maintaining blade loading at all times in order to maintain main rotor blade rotation. The fractured main rotor blade was "a purely upward bending moment which could only have occurred if the blade rpm had dramatically slowedIf totally unloaded, the blade rpm can deteriorate as fast as 120 rpm/sec." Normal rotor blade rpm is 320 to 400 rpm. If rotor blade rpm were allowed to drop and the velocity of air moving through the rotor system were to increase, severe blade "flapping" would result. The rotor head had been subjected to

NTSB ID: DEN02LA103

Occurrence Date: 09/08/2002

Occurrence Type: Accident

Narrative (Continued)

severe blade flapping as evidenced by the pounding and mushrooming of the roll pillow blocks and the bent hub bar. The authors said there is no in-flight maneuver that can lead to blade flapping at normal rotor rpms. Only the unloading of the rotor blades will do this.

FAA's Civil Aeromedical Institute (CAMI) conducted a toxicological screen on specimens taken from the pilot and found 2.024~(ug/mL,~ug/g) paroxetine in the blood. According to a CAMI toxicologist, paroxetine is an antidepressant and contraindicated. Some of the adverse effects include drowsiness, muscle weakness, agitation, and tremors." When advised of these results, the physician/co-builder of N551SA contacted the pilot's personal physician and learned that he had prescribed the drug for the treatment of fibromyalgia, a condition manifested by muscle soreness.

NTSB ID: DEN02LA103

Occurrence Date: 09/08/2002

AVIATION Occurred				rrence Type: Accident									
Landing Facility/Approach Inf	formation												
Airport Name Airpo			Airport	ID:		Airport Elevation Runway Ft. MSL			way Used Runway Length			Runw	ay Width
Runway Surface Type: Unknown									<u> </u>				
Runway Surface Condition: Unkno	vwn												
Halina													
Type Instrument Approach: Unkno	wn												
VFR Approach/Landing: Unknown	1												
Aircraft Information													
Aircraft Manufacturer Adler			1	Model/S SA-1	Series					Serial 001	Number		
Airworthiness Certificate(s): Exper	rimental (Special)		`										
- The following Continuous (continuous following)													
Landing Gear Type: Tricycle													
	Number of Seats: 1	1			Max Gross W				er of En	r of Engines: 1			
Engine Type: Reciprocating			_	Engine Manufacturer: Model/Series: Potax 912WLS						Rated Powe 100 HP			
- Aircraft Inspection Information													
Type of Last Inspection			Date o	Date of Last Inspection Time Sir				nce Last Insp	Airfram	ne Tot	tal Time		
Conditional			06/20	06/2002					44 Hours			44 Hours	
- Emergency Locator Transmitter (I	ELT) Information												
ELT Installed? No ELT Operated? ELT Aided in Locating Accident Site?													
Owner/Operator Information													
Registered Aircraft Owner  Street Address On File													
Steven H. Adler			Cit	City							State		Zip Code
			Str	Broomfield Street Address									80020
Operator of Aircraft				001710		Reg	d Aircr	aft Owner					
Same as Reg'd Aircraft Owner				City						State	•	Zip Code	
Operator Does Business As:					Operator Designator Code:								
- Type of U.S. Certificate(s) Held: N													
Air Carrier Operating Certificate(s):													
					<u> </u>								
Operating Certificate:					Operator C	Certific	ate:						
Regulation Flight Conducted Under	: Part 91: Genera	l Aviat	ion										
Type of Flight Operation Conducted	i: Personal												
	J	FACTU	JAL R	REPOF	RT - AVIATI	ON							Page 2

NTSB ID: DEN02LA103

Occurrence Date: 09/08/2002

AVIATI	Occurrence Type: Accident												
First Pilot Information													
Name					City					State	e Da	ite of Birth	Age
On File On Fil										On F	ile O	n File	51
Sex: M Seat Occupied:	eer				Cert	ificate	Number	: On File					
Certificate(s): Private													
Airplane Rating(s): Single-engine Land													
Rotorcraft/Glider/LTA: Gyroplane													
Instrument Rating(s): None													
Instructor Rating(s): None													
Type Rating/Endorsement for Accident/Incident Aircraft?  Current Biennial Flight Review? 02/2002													
Medical Cert.: Class 3	Medica	al Cert. Status	s: Valid Med	dicalw/ wa	aivers/lin	n.		Г	Date of La	st Med	dical Exa	m: 04/2001	
- Flight Time Matrix	All A/C	This Make Airplane Airplane Night and Model Single Engine Mult-Engine			Actual	Instrument ual Simulated		R	otorcraft	Glider	Lighter Than Air		
Total Time	280	44	72			3			3	3	208		
Pilot In Command(PIC)	222	44	42							+	180		
Instructor		4.4				-		$\dashv$		+			
Last 90 Days Last 30 Days	44 18	44 18								+	44 18		
Last 24 Hours	3	3								+	3		
Seatbelt Used? Yes			Used? Yes			oxico	ology Pe	erforme	ed? No			nd Pilot? No	
Seatbelt Used? Yes Shoulder Harness Used? Yes Toxicology Performed? No Second Pilot? No													
Flight Plan/Itinerary													
Type of Flight Plan Filed: No	one												
Departure Point						State		Airport Identifier			Departure Time		Time Zone
Broomfield							со вјс			0900			MDT
Destination						State		Airpor	t Identifier				
Local Flight BJC													
Type of Clearance: None													
Type of Airspace: Class	E												
Weather Information													
Source of Briefing: Unknown													
Method of Briefing: Unkno	wn												
			FACTUAL	REPORT	- AVIA	TION	1						Page 3

NTSB ID: DEN02LA103

Occurrence Date: 09/08/2002

Occurrence Type: Accident

	ETYBORY		Occurrent	ce Type:	Accide	nt								
Weather Information														
WOF ID	Observation Time	Time Zone	WOF Elevat	ion	WOF Distance From Accident Site				Direction From	n Accident Site	)			
DEN	0953	MDT	5431 Ft	MSL	25 NM					135 Deg. Mag.				
Sky/Lowes	st Cloud Condition: Fev	v				9000 Ft. A	.GL	Condition o	of Ligh	nt: Day				
Lowest Ceiling: None Ft. AGL Visibility: 10 SM Altimeter							meter:	30.12	"Hg					
Temperatu	nperature: 24 °C Dew Point: 8 °C Wind Direction: 140 Density Altitude: 7024							Ft.						
Wind Spee	ed: 4	Gusts:		Weath	Weather Condtions at Accident Site: Visual Conditions									
Visibility (F	RVR): Ft	Visibilit	y (RVV)	SM	Intensi	ty of Precipi	itation:							
Restriction	Restrictions to Visibility: None													
Type of Precipitation: None														
Accident Information														
Aircraft Damage: Destroyed Aircraft Fire: Ground Aircraft Explosion None														
Classificati	ion: U.S. Registered/l	J.S. Soil												
- Injury Su	mmary Matrix	Fatal	Serious Mino	or	None	TOTAL	T							
First Pi	ilot	1				<u> </u>	1							
Second	d Pilot						7							
Studen	nt Pilot						7							
Flight I	Instructor						7							
Check	Pilot						7							
Flight E	Engineer						7							
Cabin /	Attendants						7							
Other (	Crew						7							
Passer	ngers						7							
- TOTAL A	ABOARD -	1				1	1							
Other 0		1					7							
- GRANE	D TOTAL -	1					1							
				·										

NTSB ID: DEN02LA103

Occurrence Date: 09/08/2002

Occurrence Type: Accident

Adminis	trative	Intorma	tion
---------	---------	---------	------

Investigator-In-Charge (IIC)

Arnold W. Scott

Additional Persons Participating in This Accident/Incident Investigation:

Mark A Schofield Aviation Safety Inspector - Airworthiness FAA Flight Standards District Office 26805 East 68th Avenue, Suite 200 Denver, CO 80249